

LEARJET

Aircraft Model	Document Type	Document Number	Document Title	Rev.	Rev. Date	Pub. Price
LEARJET 20	Manual	M-LRJ24 (DHP-G-25-1)	Thrust Reverser TR3000 AMM	02	7/30/2010	NORDAM
LEARJET 20	Manual	M-LRJ25 (DHP-G-25-1)	Thrust Reverser TR3000 IPC	01	7/30/2010	NORDAM
LEARJET 20	Manual	M-LRJ36	Thrust Reverser Accumulator Modification STC No. ST10472SC	IR	10/17/2005	BOMBARDIER
LEARJET 20	Service Bulletin	SB 25-1	Thrust Reverser Hydraulic Relief Valve	IR	7/14/1973	NORDAM
LEARJET 20	Service Bulletin	SB 25-11	Airspeed/Mach Warning Indication And Airspeed Placard	01	9/15/1978	NORDAM
LEARJET 20	Service Bulletin	SB 25-12	Relief Valve Restrictor	IR	8/28/1975	NORDAM
LEARJET 20	Service Bulletin	SB 25-13	Thrust Reverser Circuit Breaker Bus	IR	12/15/1975	NORDAM
LEARJET 20	Service Bulletin	SB 25-14B	Squat Switch Installation	B	6/26/1976	NORDAM
LEARJET 20	Service Bulletin	SB 25-15	Relocation of Auxiliary Latch Solenoid Connector	01	9/28/1977	NORDAM
LEARJET 20	Service Bulletin	SB 25-16	Addition of Diodes in Normal Side of Normal/Emergency Stow Switch Circuit	IR	5/4/1977	NORDAM
LEARJET 20	Service Bulletin	SB 25-17	VMO Increase (Model 23)	IR	9/15/1978	NORDAM
LEARJET 20	Service Bulletin	SB 25-18	Replacement of the Auto-Pilot Release Cover	IR	4/3/1981	NORDAM
LEARJET 20	Service Bulletin	SB 25-19	Installation of Rivets in the Upper Nacelle	IR	8/25/1986	NORDAM
LEARJET 20	Service Bulletin	SB 25-20	Throttle Quadrant Lockplate Replacement	IR	6/5/1995	NORDAM
LEARJET 20	Service Bulletin	SB 25-3A	Thrust Reverser Door Hinge Weld	A	8/20/1973	NORDAM
LEARJET 20	Service Bulletin	SB 25-4	Thrust Reverser Ball Spline Nut Adjustment Screws	IR	8/21/1973	NORDAM
LEARJET 20	Service Bulletin	SB 25-5	Thrust Reverser Cylinder	IR	10/11/1973	NORDAM
LEARJET 20	Service Bulletin	SB 25-6	Deletion Of Thrust Reverser Gear Down Interlock	IR	1/16/1974	NORDAM
LEARJET 20	Service Bulletin	SB 25-8	Squat Switch Wiring	IR	3/6/1974	NORDAM
LEARJET 20	Service Bulletin	SB 25-9A	Mis-identification Of Emergency Circuit Breaker	A	9/6/1974	NORDAM
LEARJET 20	Service Bulletin	SB 3000 76-01	Throttle Quadrant Cover And Throttle Lever Lock Inspection	IR	9/17/2009	NORDAM
LEARJET 20	Service Bulletin	SB 3000 76-02	Throttle Quadrant - Modification of Throttle Quadrant Cover	IR	9/17/2009	NORDAM
LEARJET 20	Service Bulletin	SB 3000 76-03	Replacement of Thrust Lever Lock Springs	IR	9/17/2009	NORDAM
LEARJET 20	Service Bulletin	SB 3000 78-22	Exhaust - Thrust Reverser - Thrust Reverser Hydraulic System - Installation of Thrust Reverser Accumulator	IR	12/6/2005	NORDAM
LEARJET 20	Service Bulletin	SB A3000 78-21	Exhaust - Thrust Reverser - Thrust Reverser Hydraulic System - Removal of Thrust Reverser Accumulator	IR	11/25/2002	NORDAM
LEARJET 30	Manual	M-LRJ13 (DHP-G-49-0)	Thrust Reverser TR4000 AMM/WDM	06	11/1/1994	NORDAM
LEARJET 30	Manual	M-LRJ13 (DHP-G-49-0)	Temporary Revision	78-01	11/20/1996	NORDAM
LEARJET 30	Manual	M-LRJ13 (DHP-G-49-0)	Temporary Revision	78-02	10/1/2004	NORDAM
LEARJET 30	Manual	M-LRJ13 (DHP-G-49-0)	Temporary Revision	78-03	3/11/2008	NORDAM
LEARJET 30	Manual	M-LRJ13 (DHP-G-49-0)	Temporary Revision	78-04	7/5/2010	NORDAM
LEARJET 30	Manual	M-LRJ13 (DHP-G-49-0)	Temporary Revision	78-05	9/12/2013	NORDAM
LEARJET 30	Manual	M-LRJ14 (DHP-B-49-0)	Thrust Reverser TR4000 IPC	01	9/15/1995	NORDAM
LEARJET 30	Manual	M-LRJ14 (DHP-B-49-0)	Temporary Revision	78-01	11/12/2014	NORDAM
LEARJET 30	Manual	M-LRJ14 (DHP-B-49-0)	Temporary Revision	78-02	11/12/2014	NORDAM
LEARJET 30	Manual	M-LRJ14 (DHP-B-49-0)	Temporary Revision	78-03	11/12/2014	NORDAM
LEARJET 30	Manual	M-LRJ18	AFMS for Learjet Model 31 Equipped with Dee Howard TR4000 Thrust Reverser System (US)	04	10/13/1994	NORDAM
LEARJET 30	Manual	M-LRJ19	AFMS for Learjet Model 31A Equipped with Dee Howard TR4000 Thrust Reverser System (US)	05	10/13/1994	NORDAM
LEARJET 30	Manual	M-LRJ20	AFMS for Learjet Model 31A Equipped with Dee Howard TR4000 Thrust Reverser System (Canada)	02	10/20/1993	NORDAM
LEARJET 30	Manual	M-LRJ21	AFMS for Learjet Model 31A Equipped with Dee Howard TR4000 Thrust Reverser System (Brazil)	IR	8/17/1995	NORDAM
LEARJET 30	Manual	M-LRJ22	AFMS for Learjet Model 35/36 & 35A/36A Equipped with Dee Howard TR4000 Thrust Reverser System (US)	04	11/17/1986	NORDAM
LEARJET 30	Manual	M-LRJ28	AFMS for Learjet Models 23 with Dee Howard Company Thrust Reverser without In-Flight Arming and Restricted to 300 Knots Vmo	C	2/9/1977	NORDAM
LEARJET 30	Manual	M-LRJ29	AFMS for Learjet Models 23 with Dee Howard Company Thrust Reverser with In-Flight Arming and Restricted to 300 Knots Vmo	E	7/12/1978	NORDAM
LEARJET 30	Manual	M-LRJ30	AFMS for Learjet Models 23 with Dee Howard Company Thrust Reverser with In-Flight Arming and Reinstated to 350 Knots Vmo	F	11/6/1978	NORDAM
LEARJET 30	Manual	M-LRJ31	AFMS for Learjet Models 24 and 25 without In-Flight Arming	A	9/22/1976	NORDAM
LEARJET 30	Manual	M-LRJ32	AFMS for Learjet Models 24 and 25 with In-Flight Arming	C	7/12/1976	NORDAM
LEARJET 30	Service Bulletin	SB 4000 78-09	Inspection of the TR4000 Thrust Reverser Attach Flange	01	6/25/2013	NORDAM
LEARJET 30	Service Bulletin	SB 49-1	Replacement of the Thrust Reverser Hydraulic Control Valve	01	1/16/1984	NORDAM
LEARJET 30	Service Bulletin	SB 49-3	Replacement of the Thrust Reverser Maximum Reverse Stop	01	2/27/1985	NORDAM
LEARJET 30	Service Bulletin	SB 49-4	Inspection for Clearance Between Thrust Reverser Hydraulic Lines and the Landing and Taxi Light Resistor Installation	01	4/10/1985	NORDAM
LEARJET 30	Service Bulletin	SB 49-5	Relocation of the Landing and Taxi Light Resistor Indicators	01	9/10/1985	NORDAM
LEARJET 30	Service Bulletin	SB 49-6	Operational Check of the Thrust Reverser Latch Position Switches	IR	10/31/1986	NORDAM
LEARJET 30	Service Bulletin	SB 49-7	Modification of the AFT Engine Mount Fairing	IR	3/17/1989	NORDAM
LEARJET 30	Service Bulletin	SB 49-8	Activation of the TR4000 Thrust Reverser Learjet Model 31	IR	1/5/1989	NORDAM
LEARJET 30	Service Letter	SL 25-1	Deletion of the Thrust Reverser Piggyback Lock Paddles	IR	1/7/1975	NORDAM
LEARJET 30	Service Letter	SL 25-2A	The Addition of Warning Lights for Emergency Stow Switches	A	5/19/1975	NORDAM
LEARJET 30	Service Letter	SL 25-3A	Throttle Quadrant Assembly with Solenoid Locks P/N 25-0570-057-75	A	5/23/1975	NORDAM
LEARJET 30	Service Letter	SL 25-4	Clarification of Thrust Reverser Procedures During Taxi	IR	5/3/1976	NORDAM
LEARJET 30	Service Letter	SL 25-5	Thrust Reverser Accumulator Air Charge	IR	9/2/1976	NORDAM
LEARJET 30	Service Letter	SL 25-6	Arming for Take-off and Landing	IR	3/27/1978	NORDAM
LEARJET 30	Service Letter	SL 49-1	Replacement of the Thrust Reverser Hydraulic Control Valve	IR	1/15/1983	NORDAM
LEARJET 30	Service Letter	SL 49-2	Replacement of the Nacelle Firewall ITT Outlet Box Assembly	01	11/14/1988	NORDAM
LEARJET 30	Service Letter	SL 49-3	Replacement of the Thrust Reverser Maximum Reverse Stop	A	4/17/1990	NORDAM
LEARJET 30	Test Set Instructions	LRJ17 (M-LRJ30-01)	Test Set Operating Instructions P/N 000-006	01	12/31/9999	NORDAM
LEARJET 45 (TR5045)	Airplane Flight Manual Supplement	M-LRJ43	Airplane Flight Manual Supplement for Learjet 45 equipped with NORDAM TR5045 Thrust Reverser System	01	7/31/2008	BOMBARDIER
LEARJET 45 (TR5045)	Manual	M-LRJ37	TRCU P/N LJ7836706-3 Maintenance Manual Supplement	08	9/13/2013	NORDAM
LEARJET 45 (TR5045)	Manual	M-LRJ38	TRCU P/N LJ7836706-3 Illustrated Parts Catalog Supplement	01	6/3/2008	NORDAM
LEARJET 45 (TR5045)	Manual	M-LRJ39	Thrust Reverser Control Unit STC No. ST10526SC Installation Instructions Manual	02	9/13/2013	NORDAM
LEARJET 45 (TR5045)	Service Bulletin	SB 142-78-0005-97	Exhaust - Thrust Reverser - Isolation Valve Change-Out	IR	6/15/1998	BOMBARDIER
LEARJET 45 (TR5045)	Service Bulletin	SB 142-78-0006-98	Exhaust - Thrust Reverser - Latch Actuator Modification (Addition of Bleed Screw)	IR	7/7/1998	BOMBARDIER

LEARJET

Aircraft Model	Document Type	Document Number	Document Title	Rev.	Rev. Date	Pub. Price
LEARJET 45 (TR5045)	Service Bulletin	SB 142-78-0007-98	Exhaust - Thrust Reverser - Relocation of Flow Control Valve	02	9/17/1999	BOMBARDIER
LEARJET 45 (TR5045)	Service Bulletin	SB 142-78-0008-98	Exhaust - Thrust Reverser - Latch Spring Check	IR	8/14/1998	BOMBARDIER
LEARJET 45 (TR5045)	Service Bulletin	SB 142-78-0009-98	Exhaust - Thrust Reverser - Fairing	01	10/10/2000	BOMBARDIER
LEARJET 45 (TR5045)	Service Bulletin	SB 142-78-0010-98	Exhaust - Thrust Reverser - Hydraulic Control Valve Change-Out	01	2/5/1999	BOMBARDIER
LEARJET 45 (TR5045)	Service Bulletin	SB 5045 78-11	Exhaust - Thrust Reverser - Primary Actuator	01	10/10/2000	BOMBARDIER
LEARJET 45 (TR5045)	Service Bulletin	SB 5045 78-12	Exhaust - Thrust Reverser - T/R Wire Harness - Switch Inspection and Replacement	IR	3/6/2003	BOMBARDIER
LEARJET 45 (TR5045)	Service Bulletin	SB 5045 78-13	Exhaust - Thrust Reverser - Application of Primer to Engine Attach Flange	IR	1/17/2012	BOMBARDIER
LEARJET 45 (TR5045)	Test Set Instructions	M-LRJ12 (M-LRJ45-01)	Test Set Operating Instructions P/N LJ7836799-1	IR	11/15/1996	BOMBARDIER
LEARJET 60	Manual	M-LRJ01	AFT Engine Mount Assembly P/N 278-0812 CMM	03	5/9/2005	BOMBARDIER
LEARJET 60	Manual	M-LRJ03	FWD Engine Mount Yoke Assembly P/N 266-0803 CMM	02	5/9/2005	BOMBARDIER
LEARJET 60	Manual	M-LRJ04	Inlet Cowl Assembly P/N 282-0211 CMM	08	5/16/2005	BOMBARDIER
LEARJET 60	Manual	M-LRJ07	Thrust Reverser Assembly P/N 282-0052 CMM	13	7/16/2013	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L71-1	Power Plant - AFT Core Nozzle - Filler Replacement	IR	4/26/1995	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L78-11	Exhaust - Thrust Reverser - Lockout Bracket - Lockout Pin Hole Enlargement	IR	8/1/1996	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L78-12	Exhaust - Thrust Reverser - Stang Fairing Assembly - Stang Tip Reinforcement, Rub Strip Installation, and Replacement of INBD Support Beam Brackets	01	5/26/1998	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L78-13	Exhaust - Thrust Reverser - Thrust Reverser Lockout Replacement	03	5/28/1998	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L78-2	Exhaust - Thrust Reverser - Secondary Lock, Addition of	IR	5/10/1995	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L78-3	Exhaust - Thrust Reverser - Replacement of Stow and Deploy Switch Brackets and Rigging Instructions Modification	IR	8/1/1996	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L78-4	Exhaust - Thrust Reverser - Secondary Lock, Modification of	IR	7/15/1995	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L78-7	Exhaust - Thrust Reverser - Firewall Bulkhead - Recessing of Thrust Reverser Wire Harness Connector	01	2/2/1996	BOMBARDIER
LEARJET 60	Service Bulletin	SB PW300L78-9	AFT Support Assembly Guide Rod Bushing Replacement	03	6/25/1996	BOMBARDIER
LEARJET 60	Service Letter	SIL 300L 78-01	Electrical Harness Installations	IR	12/7/2007	BOMBARDIER