

CESSNA

ATTENTION! NORDAM IS NOT LICENSED TO DISTRIBUTE ANY CESSNA DOCUMENTATION

Aircraft Model	Document Type	Document Number	Document Title	Rev.	Rev. Date	Sold By:
BRAVO	Manual	M-CES05	Cessna Bravo Thrust Reverser Assembly P/N 53ND-78002 CMM	08	5/10/2019	CESSNA
BRAVO	Service Bulletin	SB CIT BV 78-1	Exhaust - Thrust Reverser- Lower Door - Addition Drain Hole	IR	2/12/1999	CESSNA
BRAVO	Service Letter	SIL-BRAVO-78-01	Lubrication Requirements for the Cessna Bravo Thrust Reverser	IR	6/30/1999	CESSNA
CITATION III	Manual	M-CES02	CMM - Thrust Reverser Assembly P/N 223-0002	12	2/11/2013	CESSNA
CITATION III	Service Bulletin	SB CIT III 78-1	Exhaust - Thrust Reverser Door - Bumper Pad Installation	IR	4/25/1983	CESSNA
CITATION III	Service Bulletin	SB CIT III 78-2	Exhaust - AFT Fairing Assembly, INBD - Replacement of Former	01	4/30/1984	CESSNA
CITATION III	Service Bulletin	SB CIT III 78-3	Exhaust - Stang Fairing Assembly - INBD - Modification of	03	11/16/1987	CESSNA
CITATION III	Service Bulletin	SB CIT III 78-4	Exhaust - Thrust Reverser - Link Assemblies, Idler/Driver - Modification of, to Correct Corrosion Problems	03	8/27/1987	CESSNA
CITATION III	Service Bulletin	SB CIT III 78-6	Exhaust - Thrust Reverser - Hinge Pin, Upper Door Strake-Replacement of	01	3/28/1988	CESSNA
CITATION III	Service Bulletin	SB CIT III 78-7	Exhaust - AFT Stang Fairing Assembly, INBD - Modification	01	11/3/1989	CESSNA
CITATION III	Service Letter	CIT III SL 78-1	Inbd Stang Fairing Screw Omission	01	4/28/1997	CESSNA
CITATION SII	Manual	M-CES03	CMM - Thrust Reverser Assembly P/N 202-0100	11	2/11/2013	CESSNA
CITATION SII	Service Bulletin	SB CIT SII 78-1	Exhaust - Thrust Reverser - Hydraulic Piping System-Inspection and Replacement of Piping Assemblies	IR	12/12/1985	CESSNA
CITATION SII	Service Bulletin	SB CIT SII 78-12	Exhaust - Thrust Reverser - Replacement of Stang Fairing Support Former	01	8/2/1996	CESSNA
CITATION SII	Service Bulletin	SB CIT SII 78-2	Exhaust - Thrust Reverser - Bumper Pad Installation-Replacement of End Plate/Replacement of Fan Duct Assembly Rivets	03	11/3/1989	CESSNA
CITATION SII	Service Bulletin	SB CIT SII 78-5	Exhaust - Thrust Reverser - Replacement of Stang Fairing Support Former	IR	2/1/1993	CESSNA
CITATION V	Manual	M-CES04	CMM - Thrust Reverser Assembly P/N 262-0001	12	6/18/2014	CESSNA
CITATION V	Service Bulletin	SB CITV 78-1	Exhaust - Thrust Reverser - Replacement of Stang Fairing Support Former	IR	2/1/1993	CESSNA
CITATION V	Service Bulletin	SB CITV 78-2	Exhaust - Thrust Reverser - Replacement of Stang Fairing Support Former	01	8/2/1996	CESSNA
CITATION V	Service Bulletin	SB CITV 78-3	Exhaust - Thrust Reverser - Replacement of Anti-Drag Fairing Assembly	03	9/5/1996	CESSNA
CITATION X	Manual	M-CES07	Test Set Operating Instructions P/N CX7836099-1	IR	10/15/1996	CESSNA
CITATION X	Manual	M-CES10	Thrust Reverser Assembly P/N CX7830500 CMM	07	9/9/2016	CESSNA
CITATION X	Service Bulletin	SB 7000CX 78-2	Exhaust - Thrust Reverser Modification 5% Takeoff Thrust Increase	02	4/10/2002	CESSNA
CITATION X	Service Bulletin	SB 7000CX 78-3	Exhaust - Thrust Reverser - Fairing - Replace Access Panel	IR	10/1/2006	CESSNA
CITATION X	Service Bulletin	SB 7000CX 78-4	Exhaust - Thrust Reverser - Outboard Fairing Assembly - Replace Fairing Access Panels	01	1/6/2009	CESSNA
CITATION X	Service Bulletin	SB-143-78-0005-96	Exhaust - Thrust Reverser Inflight Stow Pin Replacement	02	9/15/1997	CESSNA
CITATION X	Service Bulletin	SB-143-78-0006-96	Exhaust - Thrust Reverser Latch Box Cover Bolt Replacement	01	9/25/1997	CESSNA
CITATION X	Service Bulletin	SB-143-78-0007-96	Exhaust - Thrust Reverser Latch Actuator Replacement	01	9/25/1997	CESSNA
CITATION X	Service Bulletin	SB-143-78-0008-97	Exhaust - Thrust Reverser Pylon Close-Out Splice	01	9/15/1997	CESSNA
CITATION X	Service Bulletin	SB-143-78-0009-98	Exhaust - Thrust Reverser Fairing Modification	IR	1/30/1998	CESSNA
CITATION X	Service Bulletin	SB-143-78-0010-98	Exhaust - Thrust Reverser Abutment Plate & Jetpipe Trim Modification	IR	12/1/1998	CESSNA
CITATION X	Service Bulletin	SB-143-78-0012-98	Exhaust - Thrust Reverser Control Valve Modification	IR	8/10/1998	CESSNA
CITATION X	Service Bulletin	SB-7000CX78-1	Exhaust - Thrust Reverser Door Latch Hook Lubrication	IR	1/13/2000	CESSNA
CITATION I/II	Manual	M-CES01	CMM - Thrust Reverser Assembly P/N 202-0000	16	3/1/2013	CESSNA
CITATION I/II	Service Bulletin	SB CIT 78-1	Exhaust - Thrust Reverser - Harness Assembly, Revision of	01	6/10/1976	CESSNA
CITATION I/II	Service Bulletin	SB CIT 78-2	Exhaust (LH) - Thrust Reverser - INBD Stang Modification	IR	4/20/1976	CESSNA
CITATION I/II	Service Bulletin	SB CIT 78-3	Lever Assembly - Feedback Control, Throttle Reverser - Replacement of	IR	6/10/1976	CESSNA
CITATION I/II	Service Bulletin	SB CIT 78-4	Exhaust - Thrust Reverser - CAM, Feedback Control, Replacement of	01	10/11/1976	CESSNA
CITATION I/II	Service Bulletin	SB CIT 78-5	Exhaust - Thrust Reverser - Feedback System CAM - Inspection of	IR	3/14/1977	CESSNA
CITATION I/II	Service Bulletin	SB CIT 78-6	Exhaust - Thrust Reverser - Mechanism Support Assembly & Feedback System CAM - Inspection & Rework	02	10/15/1977	CESSNA
CITATION I/II	Service Bulletin	SB CIT 78-8	Exhaust - Thrust Reverser Door - Bumper Pad Installation	02	3/23/1987	CESSNA

CITATION I/II	Service Bulletin	SB CIT 78-9	Exhaust - Thrust Reverser - Modification of INBD Stang Fairing	IR	1/15/1981	CESSNA
CITATION I/II	Service Letter	CIT 78-7	Exhaust - Thrust Reverser-Mechanism Support	IR	6/1/1977	CESSNA
ENCORE	Manual	M-CES08	CMM - Thrust Reverser Assembly P/N 03ND-78002	07	6/27/2012	CESSNA
SOVEREIGN	Manual	M-CES09	CMM - Thrust Reverser Assembly P/N 07ND78002	05	5/15/2004	CESSNA
SOVEREIGN	Service Bulletin	SB CIT SV 78-01	Exhaust - Thrust Reverser - Replace the Thrust Reverser Door Seals	01	8/31/2005	CESSNA
SOVEREIGN	Service Bulletin	SB CIT SV 78-02	Exhaust - Thrust Reverser - Replace the Primary Actuator Assembly	01	5/5/2005	CESSNA
SOVEREIGN	Service Bulletin	SB CIT SV 78-03	Exhaust - Thrust Reverser - Lower Door - Addition of Drain Hole in Inner Skin	01	10/31/2006	CESSNA
SOVEREIGN	Service Bulletin	SB CIT SV 78-04	Exhaust - Thrust Reverser - Add Safety Wire to Latch Hook Bolts	01	6/12/2007	CESSNA
SOVEREIGN	Service Bulletin	SB CIT SV 78-05	Exhaust - Thrust Reverser - Maintenance Lock Assembly Replacement	IR	8/30/2007	CESSNA
CITATION XL/XLS/XLS+	Manual	M-CES06	CMM - Thrust Reverser Assembly P/N 64ND-78002	07	3/20/2019	CESSNA
CITATION XL/XLS/XLS+	Service Bulletin	SB CIT XL 78-1	Exhaust - Thrust Reverser - Inboard Stang Fairing - Removal of Fasteners Concealed by Pylon	IR	7/14/1998	CESSNA
CITATION XL/XLS/XLS+	Service Bulletin	SB CIT XL 78-2	Exhaust - Thrust Reverser - Lower Door - Addition of Drain Hole	IR	2/12/1999	CESSNA
CITATION XL/XLS/XLS+	Service Bulletin	SB CIT XL 78-3	Exhaust - Thrust Reverser - Hydraulic Tubes Inspection and Replacement	02	9/15/2010	CESSNA
CITATION XL/XLS/XLS+	Service Bulletin	SB CIT XL 78-4	Exhaust - Thrust Reverser - Replace Thrust Reverser Hydraulic Actuator	IR	6/13/2013	CESSNA