

HAWKER/BEEHCRAFT

Aircraft Model	Document Type	Document Number	Document Title	Current Rev.	Current Rev. Date	Sold By
1000	Manual	M-RAH01	AFT Engine Mount P/N 266-0812 CMM	01	4/30/1999	BEEHCRAFT
1000	Manual	M-RAH03	FWD Engine Mount Yoke Assembly P/N 266-0803 CMM	IR	11/11/1997	BEEHCRAFT
1000	Manual	M-RAH04	Inlet Cowl Assembly P/N 266-0101 CMM	01	1/28/2000	BEEHCRAFT
1000	Manual	M-RAH08	Thrust Reverser Assembly P/N 266-0002 CMM	10	3/31/2000	BEEHCRAFT
1000	Manual	M-RAH08	Temporary Revision	78-1	8/25/2000	BEEHCRAFT
1000	Manual	M-RAH08	Temporary Revision	78-2	3/15/2002	BEEHCRAFT
1000	Service Bulletin	SB PW300 54-6	Nacelles/Pylons - Pylon Firewall - Addition of Mounting Holes for T/R Secondary Lock Electrical Connector	IR	10/20/1995	BEEHCRAFT
1000	Service Bulletin	SB PW300 54-7	Nacelles/Pylons - Lower Engine Access Cowl - Oil Drain Grommet Installation	IR	8/1/1996	BEEHCRAFT
1000	Service Bulletin	SB PW300 71-6	Nacelle - Power Plant - Outer Fan Duct - Reinforcement of	01	12/20/1992	BEEHCRAFT
1000	Service Bulletin	SB PW300 71-7	Nacelle - Exhaust - Addition of Auxiliary Gearbox Breather Tube Assembly Gasket	IR	8/30/1994	BEEHCRAFT
1000	Service Bulletin	SB PW300 71-9	Power Plant - AFT Core Cowl Nozzle - Filler Replacement	IR	4/29/1995	BEEHCRAFT
1000	Service Bulletin	SB PW300 78-11	Exhaust - Thrust Reverser - Firewall Bulkhead	01	6/17/1997	BEEHCRAFT
1000	Service Bulletin	SB PW300 78-12	Exhaust - Thrust Reverser - Assembly Mount Flange Fastener Inspection and Replacement	IR	10/18/1996	BEEHCRAFT
1000	Service Bulletin	SB PW300 78-13	Exhaust - Thrust Reverser - Stang Fairing Assembly Stang Tip Reinforcement and Rub Strip Installation	01	10/22/1999	BEEHCRAFT
1000	Service Bulletin	SB PW300 78-14	Exhaust - Thrust Reverser - AFT Support Assembly - Guide Rod Bushing Replacement	IR	11/10/1997	BEEHCRAFT
1000	Service Bulletin	SB PW300 78-6	Exhaust - Thrust Reverser - Replacement of Stow and Deploy Switch Brackets and Rigging Instructions Modification	IR	8/1/1996	BEEHCRAFT
1000	Service Bulletin	SB PW300 78-8	Exhaust - Thrust Reverser - Secondary Lock	01	11/1/1995	BEEHCRAFT
1000	Service Letter	PW300 54-01	Nacelles/Pylons - Lower Engine Access Cowl - Oil Drain Grommet Installation and 50 Hour Flight Evaluation	02	2/19/1996	BEEHCRAFT
1000	Service Letter	PW300 71-01	Inlet Cowl FOD Inspection	IR	2/5/1996	BEEHCRAFT
4000	Manual	M-RAH12	Upper Cowl Door Assembly P/N 01ND-71102 CMM	02	11/27/2007	BEEHCRAFT
4000	Manual	M-RAH13	Inlet Cowl Assembly P/N 01ND-71601 CMM	02	11/27/2007	BEEHCRAFT
4000	Manual	M-RAH14	Thrust Reverser Assembly P/N 01ND-78002 CMM	03	8/15/2013	BEEHCRAFT
4000	Manual	M-RAH15	Lower Cowl Door Assembly P/N 01ND-71101 CMM	01	11/27/2007	BEEHCRAFT
4000	Service Bulletin	SB PW308A 71-01	Power Plant - Engine Drains - IGV Drain Tube Replacement	01	12/3/2008	BEEHCRAFT
4000	Service Bulletin	SB PW308A 71-02	Power Plant - Electrical Harnesses - Harness Routing Modification	IR	6/3/2008	BEEHCRAFT
4000	Service Bulletin	SB PW308A 71-03	Power Plant - Electrical Harnesses - RH AC Generator Power Cable Clamping Modification	IR	6/14/2010	BEEHCRAFT
4000	Service Bulletin	SB PW308A 75-01	Air - Engine Anti-Icing - Anti-Ice Bleed Air Valve Replacement	IR	7/16/2013	BEEHCRAFT
4000	Service Bulletin	SB PW308A 78-01	Exhaust - Thrust Reverser - Stang Fairing - Rivet Inspection / Installation	01	9/1/2010	BEEHCRAFT
4000	Service Bulletin	SB PW308A 78-02	Exhaust - Thrust Reverser - Lower Thrust reverser Door - Addition of Drain Holes	02	1/17/2012	BEEHCRAFT
4000	Service Bulletin	SB PW308A 78-03	Exhaust - Thrust Reverser - Hydraulic Shutoff Valve and Hydraulic Isolation Valve/Pressure Switch Torque Modification	IR	7/6/2011	BEEHCRAFT
4000	Service Bulletin	SB PW308A 78-04	Exhaust - Thrust Reverser - Nozzle - Corrosion Inspection and Repair	IR	1/5/2012	BEEHCRAFT
4000	Service Bulletin	SB PW308A 78-05	Exhaust - Thrust Reverser - Forward and Aft harnesses - Switches Adjustment	01	8/13/2012	BEEHCRAFT
4000	Service Bulletin	SB PW308A 78-06	Exhaust - Thrust Reverser - Stow And Deploy Hydraulic Hoses - Accomplishment of Eaton Service Bulletin No. AE8NN-72-12	IR	4/10/2015	BEEHCRAFT
4000	Service Bulletin	SB PW308A 78-07	Exhaust - Thrust Reverser - Thrust Reverser Stow Hydraulic Hose - Clamp Inspection	IR	4/10/2015	BEEHCRAFT
800A (TR5000BA)	Manual	M-RAH16	Switch Adjustment Test Set Instructions P/N 5475601-1	IR	7/15/1996	NORDAM
800A (TR5000BA)	Manual	M-RAH17	TR5000 Maintenance Manual	07	10/22/2015	NORDAM
800A (TR5000BA)	Manual	M-RAH18	TR5000 Illustrated Parts Catalog	04	9/8/2008	NORDAM
800A (TR5000BA)	Manual	M-RAH18	Temporary Revision	78-01	9/3/2014	NORDAM
800A (TR5000BA)	Manual	M-RAH18	Temporary Revision	78-02	9/3/2014	NORDAM
800A (TR5000BA)	Manual	M-RAH18	Temporary Revision	78-03	9/3/2014	NORDAM
800A (TR5000BA)	Manual	M-RAH21	AFMS for British Aerospace BAe 125 Series 800A with Dee Howard TR5000BA Thrust Reverser System (Canada)	01	10/20/1993	NORDAM
800A (TR5000BA)	Manual	M-RAH22	AFMS for British Aerospace BAe 125 Series 800A with Dee Howard TR5000BA Thrust Reverser System (US)	05	7/21/1995	NORDAM
800A (TR5000BA)	Service Bulletin	SB 54-1	Rewiring the Throttle Idle Switch	IR	3/2/1987	NORDAM

800A (TR5000BA)	Service Bulletin	SB 54-2	Relocation of Thrust Reverser Control Relay Box	IR	4/15/1988	NORDAM
800A (TR5000BA)	Service Bulletin	SB-54-78-0003-97	Thrust Reverser Latch Actuator Replacement	IR	1/21/1998	NORDAM
800A (TR5000BA)	Service Letter	SL54-1	Replacement of the Master Warning System Printed Circuit Board Input	IR	2/18/1988	NORDAM
800A (TR5000BA)	Service Letter	SL54-2	Replacement of Thrust Reverser Control Valve Tube Fitting Nuts	IR	2/6/1989	NORDAM
800A (TR5000BA)	Service Letter	SL54-3	Replacement of Jamnuts in Hydraulic Installation	IR	4/26/1990	NORDAM
800XP (TR5000BR)	Service Bulletin	SB 5000BR 78-08	Thrust Reverser Fan Duct - Inspection Replacement of Fasteners	IR	10/4/2000	BEECHCRAFT
800XP (TR5000BR)	Service Bulletin	SB 5000BR 78-09	Exhaust - Fan Duct - Corrosion Inspect Repair	01	4/30/2001	BEECHCRAFT
800XP (TR5000BR)	Service Bulletin	SB 5000BR 78-10	Exhaust - Thrust Reverser - Thrust Reverser Doors - Addition of Drain Holes	02	8/25/2004	BEECHCRAFT
800XP (TR5000BR)	Service Bulletin	SB-145-78-0002-95	Thrust Reverser Retrofit	01	9/15/1995	BEECHCRAFT
800XP (TR5000BR)	Service Bulletin	SB-145-78-0003-95	Thrust Reverser Afterbody Retrofit	IR	9/20/1995	BEECHCRAFT
800XP (TR5000BR)	Service Bulletin	SB-145-78-0004-95	Thrust Reverser Fan Flap Hardware Replace	IR	1/8/1996	BEECHCRAFT
800XP (TR5000BR)	Service Bulletin	SB-145-78-0005-96	Thrust Reverser Actuator Inspection	IR	4/18/1996	BEECHCRAFT
800XP (TR5000BR)	Service Bulletin	SB-145-78-0006-96	Hardware Change Thrust Reverser to Afterbody Assembly	IR	8/22/1996	BEECHCRAFT
800XP (TR5000BR)	Service Bulletin	SB-145-78-0007-98	Thrust Reverser Latch Actuator Replacement	IR	3/16/1996	BEECHCRAFT
800XP (TR5000BR)	Service Letter	SIL5000BR 78-01	NORDAM Service Bulletin No. 5000BR 78-10	IR	8/20/2004	BEECHCRAFT
Beechjet 400A/Hawker 400XP	Manual	M-RAB01	CMM - Thrust Reverser Assembly P/N 225-0002 and 225-0012	19	6/10/2014	BEECHCRAFT
Beechjet 400A/Hawker 400XP	Service Bulletin	SB BJ400 78-2	Exhaust - Thrust Reverser - Inspection and Modification of Doors and Fairings	IR	11/20/1991	BEECHCRAFT
Beechjet 400A/Hawker 400XP	Service Bulletin	SB BJ400 78-3	Exhaust - Thrust Reverser - Replace the Thrust Reverser Wire Harness	IR	4/17/2006	BEECHCRAFT
Beechjet 400A/Hawker 400XP	Service Bulletin	SB BJ400 78-4	Exhaust - Thrust Reverser - Door - Doubler Installation	IR	2/23/2010	BEECHCRAFT
Beechjet 400A/Hawker 400XP	Service Bulletin	SB BJ400 78-5	Exhaust - Thrust Reverser - Replacement of Stang Fairing Support Former	02	8/2/1996	BEECHCRAFT
Beechjet 400A/Hawker 400XP	Service Bulletin	SB MU400 78-1	Door - Bumper Pad Installation - Replacement of End Plate/Fan Duct	02	11/3/1989	BEECHCRAFT
Beechjet 400A/Hawker 400XP	Service Letter	SIL BJ 400 78-01	Availability of New Thrust Reverser Stow Switch	IR	7/26/1999	BEECHCRAFT