

## DASSAULT

Aircraft Model	Document Type	Document Number	Document Title	Current Rev.	Current Rev. Date	Sold By
FALCON 20	Manual	M-DAF13	Thrust Reverser TR5020 AMM	03	6/1/1991	NORDAM
FALCON 21	Manual	M-DAF13	Temporary Revision	1	10/3/1994	NORDAM
FALCON 22	Manual	M-DAF13	Temporary Revision	2	11/2/1995	NORDAM
FALCON 20	Manual	M-DAF14	Thrust Reverser TR5020 IPC	05	6/1/1996	NORDAM
FALCON 20	Manual	M-DAF15	AFMS for Mystere Falcon20-( ) 5 equipped with Dee Howard TR5020 Thrust Reverser System	10	3/9/1999	NORDAM
FALCON 20	Manual	M-DAF16	Performance Manual Supplement	01	3/16/1993	NORDAM
FALCON 20	Service Bulletin	SB 5020 78-01	Engine Exhaust - Fan Duct - Inspection and Repair	01	12/20/2000	NORDAM
FALCON 20	Service Bulletin	SB-TR-78-0002-92	TR5020 Throttle Exchange	IR	4/29/1992	NORDAM
FALCON 20	Service Letter	SL89-1	Thrust Reverser Activation Kits 89-003, 89-005, 89-006, 89-008 through 89-010, & 89-012 through 89-018	02	3/31/1990	NORDAM
FALCON 20	Service Letter	SL89-2	Thrust Reverser Activation Kit 89-012 through 89-018	IR	3/26/1990	NORDAM
FALCON 20	Service Letter	SL89-3	Replacement of 8911300-9 and 8911300-17 Throttle Assembly with 8911341-1 Throttle Assembly	02	11/6/1990	NORDAM
FALCON 20	Service Letter	SL89-4	Replacement of 8953115-3 Fork Fitting Assembly with 8953115-19 for Fork Fitting Assembly	IR	3/20/1991	NORDAM
FALCON 20	Service Letter	SL-89-78-0001-92	Notification of Changes in Airplane Performance with TFE731-5AR-4C Engines	IR	3/20/1991	NORDAM
FALCON 20	Service Letter	SL-89-78-0003-93	TR5020 Fan Duct Inner Skin Inspection	02	11/10/1994	NORDAM
FALCON 20	Service Letter	SL-89-78-0008-97	Exhaust - Replacement of Thrust Reverser Latch Actuator	IR	11/19/1997	NORDAM
FALCON 2000	Manual	M-DAS01	Test Set Operating Instructions P/N DS246	IR	7/15/1996	DASSAULT
FALCON 2000	Service Bulletin	SB-123-78-0003-97	Exhaust - Thrust Reverser - Abutment Plate Replacement	IR	10/27/1997	DASSAULT
FALCON 2000	Service Letter	SIL-6000 78-01	NDT at 'C' Internal Inspections	IR	6/23/2000	DASSAULT
FALCON 2000	Service Letter	SIL-6000 78-02	Inspection and Cleaning Requirements	IR	6/27/2000	DASSAULT
FALCON 2000EX	Manual	M-DAF03	Inlet Cowl Assembly P/N 06ND71600 CMM	02	3/30/2015	DASSAULT
FALCON 2000EX	Manual	M-DAF04	Upper Cowl Door Assembly P/N 06ND71102 CMM	01	2/15/2008	DASSAULT
FALCON 2000EX	Manual	M-DAF05	Lower Cowl Door Assembly P/N 06ND71101 CMM	03	3/30/2015	DASSAULT
FALCON 2000EX	Manual	M-DAF06	Thrust Reverser Assembly P/N 06ND78001	03	6/1/2013	DASSAULT
FALCON 2000EX	Manual	M-DAF07	FWD Engine Mount Yoke Assembly and Sleeve P/N 06ND71204 and 06ND71205 CMM	01	2/15/2008	DASSAULT
FALCON 2000EX	Service Letter	SIL 2000X 78-01	Servicing of Thrust Reverser Assembly - Lubrication	IR	4/20/2005	DASSAULT
FALCON 2000EX	Service Letter	SIL 2000X 78-02	Nacelle Thermal Anti-Ice System Fault Indications	IR	11/17/2005	DASSAULT
FALCON 2000EX	Service Letter	SIL 2000X 78-03	Fill Air Starter With Oil After Air Starter Removal / Installation	IR	4/12/2006	DASSAULT